



ACEG
Ringlaan 39
1853 - Strombeek-Bever
BTW nr: BE0846.351.031
www.aceg.be
Tel: 02 880 88 90

JOB OVERZICHT

#####

1540 Heme
Belgie

Decoster.hans@telenet.be

Opdrachtnummer:	Datum:	Adres	Inspecteur
643895	26/04/2022	1540 Heme Lorengstraat 1	Michael De Landsheer

ACEG					Verantwoordelijkheid klant				
Rapportnummer	Type inspectie	ID-label	Klantreferentie	Besluit	Opmerkingen	Prioritelt Inbreuk	Mogelijke oplossing	Door wie?	Tegen
753285	PC.STK.02 Stookolietankkeuringen ondergronds			Conform					

Fuel oil tank underground

Conclusion: The tank can remain in service

Next inspection: 26/4/2027

Inspection date: 26/04/2022

Inspector: Michael De Landsheer

Mentor:

ID Label:

Klantreferentie:

Measuring device: Testo 312-4

Serial number: 62055476

Location of the inspection

Street name Lorengstraat
Street number 1
Number
Postcode 1540
Suburb Heme
Country Belgium

Owner

Name ~~XXXXXXXXXX~~
Street name Lorengstraat
Street number 1
Box number
Postcode 1540
Suburb Heme
Country Belgium

Installer

Name -
VAT -
Phone -
Email -

Type

Certificate of conformity tank inspection Flanders limited research according to VLAREM and KB 21/10/1968

TANK

Position of tank Not accessible underground
Type of tank Not classified: private & < 5000L / 6000kg
Content of tank <5000 L
Date of installation Prior to 01/08/1995 (existing)

Existing tank

ACCESS DOOR

Condition of access door

Density access door

Pollution around tank

Condition of the lid

Present

Yes

No

Inspection

OK

NOK



Present

Yes

No

Inspection

OK

NOK



PIPES

Connections (venting, filling)

Condition of pipes (venting, filling)

Outlet pipes

Conditions of supply pipes



	Present		Inspection	
	Yes	No	OK	NOK
Condition of return pipes	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Heating oil filter	<input checked="" type="radio"/>	<input type="radio"/>		
Heating oil filter leaks			<input checked="" type="radio"/>	<input type="radio"/>
TANK				
General condition of tank			<input checked="" type="radio"/>	<input type="radio"/>
Previous certificate	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

	Present		Inspection	
	Yes	No	OK	NOK
ACCESSORIES				
LEVEL MEASUREMENT (preferred but not required)				
Level bar	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Mechanical	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Pneumatic	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Ultrasonic	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
OVERFILL PREVENTION (one must be present)				
Visual	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Electronic probe	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
LEAK DETECTION (one must be present)				
Liquid	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Underpressure	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Overpressure	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Sounding wells	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Other	<input type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

	TESTING		Remarks
	OK	NOK	
Water and sediment sampling	<input checked="" type="radio"/>	<input type="radio"/>	Loss of pressure 0 mbar/h Potential -604mV
Density control: Underpressure	<input checked="" type="radio"/>	<input type="radio"/>	
Potential measurement	<input checked="" type="radio"/>	<input type="radio"/>	
Potential difference measurement is not possible			

REMARKS - INFRINGEMENTS - NOTES